



Invoice Number	A-1001				
Vehicle Make	Nissan Frontier	Colour		Year	2023
VIN Number	1N6ED1CM9PN635744	Registration	BW 65725	Mileage	137650
Customer Name	Carnetwork inc.	Invoice Date	July 4, 2026		
Customer Number		Payment Method			

Description of work completed:	I took out all the electrical repairs cost and I also reduce the diag time to just an hour even though it took me so much time to figure out the harness was damage which resulted in both the low pressure fuel pump and fuse to be burnt.
--------------------------------	---

Parts And Charges	Quantity	Unit Pricing	Total
Remove fuel tank to change fuel pump	3.00	\$100.00	\$300.00
Diagnose no start Electrical wire harness burnt under truck bed	1.00	\$100.00	\$100.00
Low pressure fuel pump	1.00	\$572.00	\$572.00
Mid pipe exhaust with muffler pan and secondary catalytic	1.00	\$980.00	\$980.00
Instal exhaust mid pipe	2.00	\$100.00	\$200.00
converter	1.00	\$0.00	\$0.00
Codes present on truck (U0109,U1001	1.00	\$0.00	\$0.00

Parts & Charges	\$2,152.00
Labour Charge	\$0.00
Sub Total	\$2,152.00
HST (13.00 %)	\$279.76
Discount	\$0.00
Total	\$2,431.76
Amount Paid	\$2,431.76
Balance Due	\$0.00